

0120/10/25 02:05:33  
Command Operation without options:-i

adapter	bn	dn	fn	dID	asic	flash	romsize	test	bios	p/n
0	09	00	00	67DF	Polaris10	R600 SPI	10000	fail	-	